

Electro-desalination of glazed tile panels – discussion of possibilities

Lisbeth M. Ottosen

Department of Civil Engineering, Technical University of Denmark, Lyngby, Denmark, lo@byg.dtu.dk

Célia Dias-Ferreira

Materials and Ceramic Engineering Department, CICECO, University of Aveiro, Campus Universitário de Santiago, 3810-193 Aveiro, Portugal, cdf@ua.pt

Alexandra B. Ribeiro

CENSE, Departamento de Ciências e Engenharia do Ambiente, Faculdade de Ciências e Tecnologia, Universidade Nova de Lisboa, Caparica, Portugal, abr@fct.unl.pt

SUMMARY: Glaze is lost from tiles in tile panels due to presence of soluble salts and this means loss of important heritage. There is no proven method for in-situ desalination of tile panels (inclusive the mortar and wall behind).

The present paper discusses the possibility to apply electro-desalination. An in-situ test has not been performed yet, but encouraging results have been obtained with different parts of the system. Single tiles from different epochs and different places in Portugal have been electro-desalinated successfully (both biscuit and interface between biscuit and glaze). Electro-desalination has also been tested on a variety of porous stones (natural stones and ceramic bricks) in laboratory scale, and no limitations for salt removal have been in relation to the brick or stone type. Also successful desalination of the mortar on the back of a tile has been obtained. Thus all parts of the wall with tile panel can be electrodesalinated.

The interface between mortar and tile can be problematic for in-situ electro-desalination in cases where the tile is partly loosened. The interface needs to be in hydraulic contact meaning that there is a continuous liquid between the materials in order for the electric field to pass and subsequent the electro-desalination to progress. Few experiments were conducted with desalination of tiles with attached mortar. The electrodes were placed on the mortar, which was desalinated to a higher degree than the biscuit. However, whether successful desalination of the biscuit through the mortar could have been obtained was not confirmed. This is a point for further research.

In-situ pilot scale tests have been performed on very salt contaminated walls without tiles. Even though the final proof of concept has not been made yet, these experiments have illustrated, that it is possible to perform the desalination from electrodes which are all placed at the same side of the wall. This can be very useful in relation to electrodesalination of tile panels. It may be possible to desalinate without any physical damage of the fragile glaze by placing the electrodes on the opposite side of the wall or to remove some tiles, place electrodes in their spaces and extract the salts from there, before the tiles are placed in place again.

KEY-WORDS: Azulejos, salt induced decay, desalination, electrokinetics



1. INTRODUCTION

Ceramic tiles, *azulejos*, are an important Portuguese cultural heritage. They have been used continuously during five centuries. Regrettably many tiles are lost due to decay. The Portuguese tiles applied in panels are designed for surface continuity, so the width of joints does not interfere with the image. Their sides are beveled and, when mounted together to form a panel, their edges contact (Mimoso et al. 2009). This may constitute a problem in cases the tiles are wet for a long period causing swelling and subsequent cracked and damaged glazing. Today many degraded tile facades are in urgent need of maintenance (Botas et al 2014).

Soluble salts are a major cause of decay, and aside from human actions, soluble salts are likely to be the most important cause of decay and loss of single tiles as well as whole panels (Mimoso et al. 2009). The damage caused by soluble salts is generally due to their accumulation and phase transition at or near to the surface of the object, or between layers, as a result of moisture transfer processes (Sawdy et al. 2008). The salts can enter the tiles from rising groundwater in the wall to which they are attached. Rain water may also be introduced through the roofs of ancient buildings (Borges et al 1997). Tiles are applied after being soaked so that they are dilated, in order that further (thermal or hydric) expansion does not cause cracking. But afterwards, they contract. Therefore, the joints may be slightly open when rain hits the panel. This will influence the distribution of salts in the wall. Mimoso et al (2009) visited different monuments around Portugal aiming to assess decay patterns, particularly when caused by salt crystallization. They concluded that the durability depends largely of the tile being defect-free and mounted on essentially dry walls. Tiles with manufacturing defects may have their glaze partially cracked or delaminated, thus offering easy routes for moisture propagation and salt crystallization.

In-situ treatment options for removal of salts to stop the decay of tile panels are few. Use of poultice techniques where a poultice is applied to the surface and the salts are transported out from the tile into the poultice by diffusion and/or advection suffer from the need for the poultice to be applied to the often fragile glazed surface, thus physical damage may be hard to avoid. Also, in areas where glaze is intact the through transfer is nil.

The present paper deals with development of electro-desalination for in-situ treatment of tile panels. A discussion of possibilities and limitations of the method for desalination of tile panels is given on basis of already published work with the method with results ranging from desalination of single tiles to wall sections (without tiles).

Tiles are placed on the wall on a bed of mortar (figure 1). It is important to remove salts from all parts during the in-situ electro-desalination, otherwise the tiles will soon be salt infected again from salts entering from mortar and wall. In this paper electro-desalination of the different parts: wall, tile bed, ceramic biscuit and glaze are first discussed separately. Influence from interfaces between the different materials/parts is then discussed and finally the possibility for in-situ electro-desalination of tile panels is evaluated, focusing on the possibility to place the electrodes around the panel to avoid any further damage.





Figure 1: Cross section of tile panel. This paper discusses electro-desalination of the four single parts followed by a discussion of in-situ treatment of tile panel and support

2. PRINCIPLE OF ELECTRO-DESALINATION

The main transport mechanism for salt ions in a moist, porous material under application of an electrical potential gradient is electromigration, which electro-desalination is based on. During the process, the concentration of dissolved salts will decrease in the porous material as the dissolved ions concentrate around the electrode of opposite polarity. The overall principle of electro-desalination is shown in figure 2. The electrode compartments consist of an inert electrode placed in a clay poultice. The electrode compartments are placed on the surface of the porous material to be desalinated. The optimal placement is determined by several factors, which are discussed later in this paper.

The dominating electrode processes are electrolysis of water: $H_2O \rightarrow 2H^+ + \frac{1}{2}O_2(g) + 2e^-$ (at the anode) and $2 H_2O + 2e^- \rightarrow 2OH^- + H_2(g)$ at the cathode. When the removed chloride ions reach the anode they can be oxidized to Cl_2 from the electrode process: $2Cl^- \rightarrow Cl_2(g) + 2e^-$. Electrolysis influences the pH around the electrodes. It is necessary to neutralize acidification at the anode in order to prevent decay of the material to be desalinated. Hendrix et al. (2011) underlined how important it is to avoid the acidification, as in experiments without pH neutralization the stones were severely damaged close to the anode. This was confirmed by Skibsted et al (2013) who reported that buffering of the acid produced at the anode was important to avoid decomposition of the stone, which was seen as increased porosity close to the anode due to dissolution of calcite in case no buffering system was used. In addition they reported indications of gypsum formations in the region closest to the anode both with and without poultice, but a higher degree of gypsum was seen in the setup without poultice.

Also in order to obtain sufficient desalination pH neutralization can be crucial. Kamran et al. 2012 showed that without neutralization at the electrodes, the desalination process in bricks stopped due to formation of a sharp transition zone between the acidic and alkaline region. This zone resulted in a large electrical potential gradient due to a local depletion of ions here. So for different reasons, the metallic electrodes should not be placed directly on the material to be desalinated.





Figure 2: Principle of electrodesalination

Carbonate rich clay poultice can be placed between the electrodes and the stone for neutralization of pH changes. Calcareous clay for brick production or a mixture of kaolinite and calcite both efficiently neutralized the acid from the anode (Ottosen et al 2012). The acid was neutralized by the CaCO₃ in the poultices. In the cathode poultice and in the porous material there may be precipitation of Ca(OH)₂ in the material as a result of the alkalinisation from the cathode (Paz-Garcia et al. 2012). Over time Ca(OH)₂ reacts with CO₂ from the air and form CaCO₃. Neither Ca(OH)₂ nor CaCO₃ are considered damaging, because aqueous solutions of calcium hydroxide (limewater) have been used for many centuries to protect and consolidate limestone. In addition to neutralizing the acid, the poultice also gives good electrical contact between metallic electrode and stone, and it serves as sink for removed ions. When the clay poultices are removed after the desalination, the ions of the salts are removed with it.

3. ELECTRO-DESALINATION OF THE DIFFERENT PARTS IN A TILE PANEL

In this chapter the experimental results with the different parts of the tile panel shown in figure 1 are discussed separately.

3.1 Single tiles – biscuit and glaze

Experiments have been reported with electro-desalination of single tiles in the laboratory (Ottosen et al 2009, 2010, 2015). The experimental setup of these is illustrated in figure 3. The tiles were placed with the glaze down and because they had dried out during indoor storage, water was sprayed on the back side of the tiles before placing the electrode compartments (poultice and inert electrode mesh) as far apart as possible. The tile and electrode compartments were wrapped in plastic to hinder evaporation of water, which would hamper the passage of electric current. A constant current was then applied to the electrodes. Moist pores are needed in order to be able to have passage of current through the biscuit. In cases, where salt decay is problematic, waster must be present at least during some periods and it is assumed that it is not neither necessary to add extra water or cover the wall as in the laboratory atmosphere with very low RH.





Figure 3: Experimental setup for desalination of single tile

The first results reported on electro-desalination of single tiles were obtained with XIX century tile segments spiked with NaCl (Ottosen et al. 2009). Removal efficiencies of 96% Cl was reached in less than 6 days.

Following this good result, experiments with spiked tiles, experiments were conducted with 18th century tiles, which had been removed from Palacio Centeno (Lisbon) during renovation due to damage of the glazing from the presence of salts. These tiles were severely contaminated with both chlorides and nitrates. The charge transfer in the electrodesalination experiments was too low in the experiments to obtain full desalination, but promising results were obtained as significant decreases (>81% Cl⁻, \sim 59% NO3⁻ and \sim 22% SO_4^{2-}) were seen. In Ottosen et al. (2015) the duration of the experiments was long enough to obtain sufficient desalination (2-3 month). There is neither a common European nor a Portuguese guideline on acceptable concentration levels for salt in building stone. To evaluate the salt concentrations the only accessible threshold values are from the Austrian ÖNORM B 3355-1 and these are chosen as a first approach here, though these limiting values are much debated. In relation to the ÖNORM the concentrations of Cl⁻ (9900 mg/kg) and especially NO3 (30,600 mg/kg) were very high in the tiles (exceeding the concentrations where desalination is advised). After the electro-desalination the concentrations of both Cl⁻ and NO3- were well below the lower level of the ÖNORM (which are respectively 300 mg Cl/kg and 500 mg NO₃-/kg, so the desalination of the biscuit was successful.

Large parts of the glaze and parts of the biscuit were lost in the Palácio Centeno tiles presumably due to salt decay. The most severe damage was seen from the outer edges towards the centre of the tile as described by Mimoso et al. (2009). Salt crystals (NaCl) were clearly identified under the lifted glaze by SEM-EDX before electro-desalination, but after the treatment no crystals were found under the glaze. Thus this important interface was successfully desalinated (Ottosen et al 2015). Salt crystals cannot directly be reached by the electric field as they overall carry no electric charge. During the electro-desalination process, the crystals must thus have been dissolved into ions in the pore solution. The spraying of water or water from the wet poultice must have penetrated to this interface



dissolving or partly dissolving salts crystals and hereby mobilizing them for electromigration. When free ions are removed, equilibrium will change towards dissolution of more crystallized salts and the new ions can subsequently be removed by electromigration, so a low and harmless concentration of salt was obtained over time. It must be investigated, if the water in salt damaged tile panels is sufficient for such dissolution of salt crystals over time.

The fraction of the applied current carried by Cl^- and NO_3^- during the desalination was very high meaning a high current efficiency. During the desalination Cl^- and NO_3^- were removed at the same rate. The initial sulphate concentration was low, but when the more mobile chloride and nitrate were removed to a low level removal of sulphate started (Ottosen et al. 2015).

An experiment with electro-desalination of a Portuguese 20th-century tile (figure 4) has also been conducted (not previously published). The average initial concentrations were 700 mg Cl⁻/kg and 930 mg SO₄²⁻/kg and thus the salt contamination was much less that the older tiles from Palacio Centeno After 3 weeks with 1 mA applied 76% Cl⁻ and 87% SO₄²⁻ were removed from the tile. Hereby it was shown that also this biscuit type can be desalinated.



Figure 4: 20th century tile used in lab experiment.

3.2 Tile bed and interface between tile bed and tile

Lime mortars have been used since ancient times in masonry, renders, plasters, and also as adhesive agents for tiles, namely between 16^{th} and mid. 20^{th} centuries. This type of mortar is known to be compatible with old masonry and ancient ceramic tiles (Russo et al. 2011).

Brammer & Sveegaard (2010) and Ferreira et al (2011) reported laboratory results with electro-desalination of three tiles from different centuries. Mortar was attached to the tiles in these investigations (see figure 5). Each of the three tiles was broken. The tiles were: 17th - century tile from the Alentejo Region (mortar very hard and unfortunately not considered original), 18th-century tile from Palacio Centeno, Lisbon (mortar very porous and loose, considered original) and 20th-century tile of unknown origin (mortar was hard, but is considered original). Initial samples were taken from both tile and mortar prior to the desalination experiments. From the first two tiles it was only one sample from both. The 20th -century tile was separated into two pieces where one was used to find the initial salt concentration and the other for the desalination experiment.

As in the experiments with single tiles, the tiles were placed with the glaze down. Water was sprayed on the mortar, which was now the upper part and the electrode compartments were placed on the mortar surface.



GlazeArch2015 International Conference Glazed Ceramics in Architectural Heritage



Figure 5: experimental tiles with mortar. (a) 17^{th} century tile from the Alentejo Region (b) 18^{th} century tile from Palacio Centeno, Lisbon (c) and 20^{th} century tile of unknown origin.

The overall conclusions from the electro-desalination experiments with tile and mortar attached were:

17th century tile: The glazing of the tile did not show sign of salt decay and the concentrations in the initial samples were also very low 93 mg Cl/kg and 130 mg NO₃/kg in the mortar and 53 mg Cl/kg and 42 mg NO₃/kg in the biscuit. Still it was decided to see if the salt content could be lowered by electro-desalination, which was the case. The removal after 7 days with about 1 mA applied were in average 51% Cl and 83% NO₃/kg in the mortar and 15% Cl and 64% NO₃ in the biscuit. Thus even at such low concentrations salt was removed in the applied electric field. The highest decrease was obtained in the mortar, but the concentration was also decreased in the biscuit (Brammer and Sveegaard, 2010).

18th century tile: Very high initial concentrations in both mortar (6600 mg Cl⁻/kg and 14,000 mg NO₃⁻/kg) and biscuit (6600 mg Cl⁻/kg and 14,000 mg NO₃⁻/kg) were found. During the 24 days of experiment the current was gradually increased from 5 to 10 to 20 mA as the voltage (reflecting the overall resistivity) was very low. From the mortar was removed 91% Cl⁻ and 84% NO₃⁻ and from the biscuit 42% Cl⁻ and 9% NO₃⁻ (Brammer and Sveegaard, 2010), (Ferreira et al. 2011). The desalination was not completed in this experiment as too



high concentrations remained, however, as the voltage was still low at the end of the experiment and as the concentrations of salt ions continuously increased in the poultice the desalination could have progressed longer (Ottosen et al 2011). The percentages of salt removal from the mortar were significantly higher than from the biscuit in this experiment.

 20^{th} century tile: Compared to the Önorm neither of Cl, NO₃⁻ and SO₄⁻ exceeded the limiting value were salt removal is advised. However, the average SO₄⁻ concentrations were high both in mortar and biscuit and the concentration varied considerably, so it was decided to perform electro-desalination even if the adapted upper limiting values from the ÖNORM were not exceeded (the concentration level falls within the category where individual evaluation is advised). This because some sulphate salts are known to be highly damaging In the reference piece the average concentrations with standard deviation were: mortar 1540 ± 1490 mg SO₄⁻²/kg and biscuit 650 ± 590 mg SO₄⁻²/kg. After electro-desalination the concentrations were: mortar 150 ± 83 mg SO₄⁻²/kg and biscuit 120 ± 32 mg SO₄⁻²/kg. This corresponds to a removal on average of 90% from the mortar and 82% from the biscuit.

The interface between mortar and tile can be problematic for in-situ electro-desalination in cases where the tile is partly loosened. If this interface is so poor that there is air filled space between them passage of current is not possible in this zone. In all three tiles the salt ions were removed better from the mortar than tile, but this may reflect that the electrode compartments were placed directly on the mortar and not the biscuit. Salt ions were removed over the interface in all cases. The adhesion mechanism between tile and mortar is ruled partially by physical forces, such as Van der Waals forces and the suction of fresh binder by the tile, and partially by chemical links. Thus, the chemical and mineralogical composition of the bonding agent, i.e. the mortar, may be critical for an appropriate bond (Russo et al. 2011). The interface can be very weak and experiences focusing on mapping interface properties, where the interface is limiting the electro-desalination process of the tile through the mortar must be obtained from experimental work, followed by finding a method where these situations can be found while the ties are still in place.

3.3 Brick and natural stone

Electrochemical desalination with carbonate rich buffer poultice at the electrodes of different porous matrices has been tested in the laboratory

- **Baked clay bricks**. Handcrafted red bricks for renovation purposes (Rôrig-Dalgaard, 2008), (Rörig-Dalgaard et al. 2012), yellow brick (Ottosen & Rörig-Dalgaard, 2007), and red bricks (Ottosen & Rörig-Dalgaard, 2009)
- **Natural stones**. Posta and cotta sandstones (Ottosen & Christensen 2012), Gotlandic Sandstone (Skibsted, 2013), Nexø sandstone (Petersen et al. 2010), and granite (Feijoo et al. 2013).

Electro-desalination was successful in every case, and thus the success for desalination of a tile panel is not considered to be dependent on the porous material of the wall itself.

The influence on electro-desalination of the interface between wall and mortar must be investigated similarly to the interface between tile and mortar. However, no such experiments have been conducted yet.



4. PILOT TESTS WITH MASONRY WITHOUT TILE

Ottosen and Hansen (2015) summarize results from four small (2-6 electrode units) and one larger (74 electrode units) in-situ pilot scale tests for electro-desalination of masonry (natural stone and brick masonry). In every case, the electrodes were placed at the same side of the wall and with alternating polarity. When the electrodes are placed like this, the electric field is strongest close to the surface, but will distribute into the wall as shown schematically in figure 6a. When the electrodes are at the same side, the concentration decreases closest to the electrodes first and over time the desalination progresses into the depth of the material (Rörig-Dalgaard, 2009). Figure 6b is an example of a pilot scale plant for electrodesalination.



Figure 6: (a) principle of electro-desalination of wall with electrodes placed at the same side of the wall and distribution of electric field lines in case of a homogeneous material. (b) Photo from a pilot scale plant for electro-desalination of walls.

Neither of the pilot scale tests can be regarded as the final proof of concept, as full desalination has not been obtained yet. Every test was unfortunately stopped before full desalination due to a limited project-duration. However, when they were stopped, the transference number for the target ion was still high, and the desalination could have progressed further if the experiment duration had been prolonged. The large pilot scale plant covered about 25 m² surface of a limestone wall of a historic warehouse. The wall was highly contaminated with NaCl (7300 mg Cl/kg in average). A total of 3.8 kg chloride corresponding to 6.3 kg NaCl was removed during the 390 days of the experiment (Ottosen et al 2012). A small pilot scale experiment was close to full desalination. The main pollutant was NaCl and the initial level varied between 1400 and 4000 mg Cl/kg. The Cl⁻ concentration in the masonry below the cathode and between the electrodes was decreased to a sufficient level in 10 cm depth (the whole depth investigated). The concentration below the anode was decreased to a level of 1800 mg Cl/kg, which was still too high compared to the ÖNORM (300 mg/kg).



5. DISCUSSION ON POSSIBLE IN-SITU DESALINATION OF TILE PANELS

In case of in-situ electro-desalination of tile panels, the electrodes should not be placed on the outer surface with the fragile glaze. As the overall transport mechanism for the salt removal is electromigration advantage can be taken of the electric field lines to distribute over a certain volume. The electric field will be strongest where the conductivity is highest, and this must be expected to be close to the surface where the salt damage also develops.

Rörig-Dalgaard (2008) conducted laboratory experiments with electro-desalination of bricks. The electrodes were placed on the same side of the brick and it was clearly shown, that the upper part of the brick (closest to the electrodes) was desalinated before the middle part, which was again desalinated before the lowest part of the stone. Ottosen et al (2014) conducted electro-desalination experiments with sandstones, which were cut in irregular shapes. Parts of the stone, which were not placed directly between the electric field, were desalinated, though later than the part between the electrodes. These two studies show experimentally, that the electrodes do not necessarily need to be on each side of the object to be desalinated. This can be utilized when desalinating tile panels. In case there are no air cavities between wall-mortar-tile, it is likely, that the desalination can be carried out from electrodes, which are placed on the surface of the wall opposite to the tiles. If it is not possible to place the electrodes here, another option could be to remove already loose tiles and place electrodes on the mortar where they were removed. The removed tiles should be desalinated ex-situ (e.g. by submersion) before placed in the tile panel again after electrodes desalination.

There are several open questions, which need to be researched and answered before the potential of electro-desalination for tile panels can be detailed evaluated. For example the walls can be more than 1 m thick. This may limit the option of placing the electrodes at each side as the electrical resistance may be very high, and also the wall may not be in hydraulic contact all through. An option may here be to place the electrodes at the same side and focus on desalinating the wall closest to the tiles only.

The solubility of the salts is a determining factor for electro-desalination. All damaging salts are soluble to some extent as it is the cycles between solubilized and nucleated which causes the decay. However, the solubility may still be very low, meaning that the electro-desalination can be very slow (years) if it depends on equilibrium changes from removing the solubilized fractions. Also, we may need to wet the wall in periods with low RH, the criterion to determine when this is needed may be based on the electrical resistance between the electrodes, however, wetting is not a preferred option, and in some cases it might also be sufficient to cover the wall during treatment to keep the moist in the wall and hinder drying trough evaporation. In the pilot scale plants performed so far on walls without tiles, wetting has though not been necessary.

When the supply of moisture and salts remains active after the electro-desalination, as for example the case if rising damp, the problem of salt induced decay will reappear over time after electro-desalination. It may be a suggestion to estimate the rate of which the salts are supplied into the masonry again and plan for a new desalination action before a damaging level reappears.



6. CONCLUSIONS

Electro-desalination of tile panels has not been tested yet, but different experiments in laboratory and pilot scale have been encouraging in relation to develop the method for this purpose. In laboratory scale single tiles have been desalinated and both the biscuit and the interface between glaze and biscuit were desalinated successfully. Mortars, several types of natural stones and baked clay bricks have been successfully desalinated with the method, too. In fact all types of porous stones have been successfully treated by electro-desalination. The coming research must focus on interfaces between the materials and how these influence the desalination. In-situ electro-desalination has been conducted at different salt-infected walls without tiles. The final proof of concept has not yet been reached, i.e. full desalination of the wall due to a too short duration, but the salts were removed at a high efficiency of the applied current. The electrodes were placed at the same side in these experiments, which could also be a solution for tile panels, either to conduct the desalination from the back side of the wall (opposite to the tiles) or by removing a few tiles and place electrodes in the gaps. These ideas however remain to be tested.

ACKNOWLEDGEMENTS

Joao Manuel Mimoso LNEC is acknowledged for getting the idea and suggesting electrodesalination to be tested on tiles and providing the first tile. Ivo Férin and colleagues (Loubet and Isabel) for providing the salt contaminated tiles.

REFERENCES

- AUSTRIAN ÖNORM B 3355-1 "Trockenlegung von Feuchtem Mauerwerk Bauwerksdiagnostik und Planungsgrundlagen" 1999
- BORGES, C., C. Caetano, J. Costapessoa, M.O. Figueiredo, A. Lourenco, M. Malhoa Gomes, T.P. Silva and J.P. Veiga *-Monitoring the removal of soluble salts from ancient tiles by ion chromatography*. Journal of Chromatography A, 770, 1997, 195-201
- BOTAS, S., M.R.S. Veiga and A.L. Velosa *Reapplication mortars for old tiles: Characteristics of tiles and mortars and selection criteria*. International Journal of Architectural Heritage, 8, 2014, 124-139
- BRAMMER, S.H. and D.A.F. Sveegaard Elektrokemisk saltfjernelse fra porøse byggematerialer med fokus på historiske kakler. BSc project, Technical University of Denmark, 2010 (In Danish)
- FEIJOO, J., X.R. Nóvoa, T. Rivas, M.J. Mosquera, J. Taboada, C. Montojo, and F. Carrera,
 Granite desalination using electromigration. Influence of type of granite and saline contaminant. Journal of Cultural Heritage 14 (2013) 365–376
- FERREIRA, C., L.M. Ottosen, I.V Christensen, S.H. Brammer and D.A.F. Sveegaard -Evaluation of Salt Removal from Azulejo Tiles and Mortars using Electrodesalination, Proceedings at XII DBMC – 12th International Conference on Durability of Building Materials and Components, Porto, Portugal, April 12-15, 2011, 8 pages
- HERINCKX S., Y. Vanhellemont, R. Hendrickx, S. Roels and H. De Clercq Salt removal from stone building materials using an electric field. In: Proceedings from the international conference on salt weathering on building and stone sculptures, I. Iannou & M. Theodoridou (eds.), Limassol, Cyprus 19-22 October 2011, 357-364



- KAMRAN, K.; M. van Soestbergen, H.P Huinink and L. Pel Inhibition of electrokinetic ion transport in porous materials due to potential drops induced by electrolysis. Electrochimica Acta 78, 2012, 229–235
- MIMOSO, J.M., A.S. Silva, M.M. Abreu, D.R Costa, T.D Goncalves and S.X. Coentro, Decay of historic azulejos in Portugal: an assessment of research needs. In proceedings from International seminar Conservation of Glazed Ceramic Tiles, Lisbon 15-16. April 2009.
- OTTOSEN, L.M. and I.V. Christensen *Electrokinetic desalination of sandstones for NaCl removal Test of different clay poultices at the electrodes*. Electrochimica Acta. 86, 2012 192-202
- OTTOSEN, L.M., L.M Christensen and I. Rörig-Dalgaard *Electrochemical desalination of* salt infected limestone masonry of a historic warehouse. Proceedings of Structural Faults and Repair (CD) Ed MC Forde, Edinburgh, Scotland, 2012, 15 pages
- OTTOSEN, L.M., C. Dias-Ferreira and A.B Ribeiro *Electrochemical desalination of historic Portuguese tiles – removal of chlorides, nitrates and sulfates.* Journal of Cultural Heritage, In press 2015
- OTTOSEN, L.M., C. Ferreira and I.V. Christensen *Electrokinetic desalination of glazed ceramic tiles preliminary results*. In proceedings from Seminar on "Conservation of Glazed Ceramic Tiles. Research and Practice" 14-16 April 2009, Lisbon, Portugal, paper 19 (10 pages)
- OTTOSEN, L.M., C.D. Ferreira and I.V. Christensen *Electrokinetic desalination of glazed ceramic tiles*. Journal of Applied Electrochemistry. 40, 2010, 1161-1171
- OTTOSEN, L.M., C. Ferreira and I.V. Christensen (2011) *Electrochemical desalination* of historic Portuguese tiles, Azulejos, in laboratory scale, Proceedings of SWBSS2011 Salt Weathering on Buildings and Stone Sculptures (eds. I. Iannou & M. Theodoridou), Limassol, Cyprus, 19-22 October, 349-356
- OTTOSEN, L.M. and H.K. Hansen *Electro-desalination of buildings suffering from salt weathering*. Xxx. Springer, In Press
- OTTOSEN, L.M. and I. Rörig-Dalgård *Electrokinetic removal of Ca(NO₃)*₂ from bricks to avoid salt induced decay. Electrochimica Acta 52(10), 2007, 3454-3463
- OTTOSEN, L.M. and I. Rörig-Dalgaard Desalination of a brick by application of an electric DC field. Materials and Structures, 42(7), 2009, 961-971
- OTTOSEN, L.M., G. Skibsted and T. Præstholm (2014) *Electrodesalination of sandstones* with irregular shapes and uneven distribution of salts. In Proceedings from SWBSS2014 3rd International Conference on Salt Weathering of Buildings and Stone Sculptures. Ed. H. De Clercq, 405-420
- PAZ-GARCIA, J.M.P., B. Johannesson, L.M. Ottosen, A. Alshawabkeh, A.B. Ribeiro and M. Rodriguez-Maroto - *Modeling of electrokinetic desalination of Brick*, Electrochimica Acta. 86, 2012, 213-222.
- PETERSEN, G., L.M. Ottosen and P.E. Jensen (2010) The possibility for using electrokinetics for desalination of sandstone with low porosity. Proceedings from 8th fib International PhD Symposium in Civil Engineering. Kgs. Lyngby, Denmark, June 20-23, 455-460



- RUSSO, A., M. R. Veiga, M. F. Vaz and A. P. Carvalho *Effect of the Conservation Treatment of Historical Ceramic Tiles on the Tensile Adhesion Strength*', International Journal of Architectural Heritage, 5(2), 2011, 241-250
- RÖRIG-DALGAARD, I. Preservation of masonry with electrokinetics with focus on desalination of murals. PhD Thesis. Department of Civil Engineering, Technical University of Denmark, 2009
- RÖRIG-DALGAARD, I., L.M. Ottosen and K.K. Hansen Diffusion and electromigration in clay bricks influenced by differences in the pore system resulting from firing. Construction and Building materials 27(1) (2012) 390-397
- SAWDY, A., A. Heritage and L. Pel (2008) A review of salt transport in porous media, assessment methods and salt reduction treatments. Proceedings from Salt Weathering on Buildings and Stone Sculptures, 22-24 October, 2008, Copenhagen, Denmark, 1-27
- SKIBSTED, G., L.M. Ottosen and P.E. Jensen Electrochemical desalination of limestone spiked with Na₂SO₄ –importance of buffering anode produced acid. Paper E in Matrix changes and side effects induced by electrokinetic treatment of porous and particulate materials. PhD thesis from Gry Skibsted, 2013, Technical University of Denmark